

Category:	Trickle Filter	Score		Score		Score
Plant:		Ozark WWTF		Towassa WWTP		Econchate WWTP
		CR		BO		AE
Inspector:						
		93.56		104.02		95.51
	AVG	93.56	AVG	104.02	AVG	95.51

Best Operated Plant	BO
Award of Excellence	AE
Certificate of Recognition	CR

Category:	< 2.5 MGD	Score		Score		Score		Score		Score
Plant:		Fairmont		Jeff Rd		Double Oak		Liberty Park		Milley's Creek
		CR		CR		CR		AE		BO
Inspector:		96.1		95.91		96.69		99.11		99.25
		84		97		93.27		94.53		94.85
	AVG	90.05	AVG	96.455	AVG	94.98	AVG	96.82	AVG	97.05

Category:	2.6-4.0 MGD	Score		Score		Score
Plant:		Hartselle		N. Shelby		Riverview
		BO		CR		AE
Inspector:		93		90.75		97.25
		97.5		86.75		87
	AVG	95.25	AVG	88.75	AVG	92.125

Category:	4.1-8.9 MGD	Score		Score		Score
Plant:		J. Earl Ham		Norm Skinner		Northport
		AE		CR		BO
Inspector:		97.75		89.25		99.5
		92.6		89.3		95.5
	AVG	95.175	AVG	89.275	AVG	97.5

Category:	> 8.9 MGD	Score		Score		Score		Score
Plant:		Athens		MUB Albert.		Cahaba		Catoma
		CR		AE		CR		BO
Inspector:		90.75		91.25		88		96.75
		96.818		101.27		93.1		101.71
		86.25		84.26		82.85		88.38

	AVG	91.534	AVG	92.765	AVG	87.975	AVG	95.045
--	------------	--------	------------	--------	------------	--------	------------	--------